## REPORT OF CHANNEL CONDITIONS 100 TO 400 FEET WIDE

(EP 1130-2-520)

PAGE I OF 1 DATE

10 September 2007

TO:

Navigation Interests

FROM:

U.S. Army Engineer District, Baltimore

P.O. Box 1715

Baltimore, Maryland 21203-1715

RIVER/HARBOR NAME AND STATE

Tilghman Island Harbor

Talbot County, Maryland

MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD

Tilghman Island Harbor Talbot County, Maryland						CHANNEL ENTERING FROM SEAWARD		
NAME OF CHANNEL		DATE OF SURVEY	AUTHORIZED PROJECT			LEFT		RIGHT OUTSIDE
			WIDTH (feet)	LENGTH (miles)	DEPTH (feet)	OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	OUTSIDE QUARTER (feet)
Tilghman Island Harbor Basin	0+000	1/Jun/2007	200	0	6	6	6	(
*Tilghman Island Harbor	0+455	1/Jun/2007	60	0	6		6	
				a				

REMARKS (Continue on reverse)

All depths refer to mean lower low water (MLLW) for the 1983 to 2001 epoch.

This information represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions at that time.

The length of the channel is reported to the nearest mile (the basin is 0.09 miles and the rest of the channel is 0.38 miles). The depths are reported to the nearest foot.

LO.Q.: E1502151.18 N381636.30 6.3 M.H. E1501938.29 N381687.67 6.1 R.O.Q.: E1501993.06 N381598.55 5.9

\*Middle Half equals minimum depth in full channel: E1503682.29 N380590.70 5.7